

PSLSB

Experiment 1 CT Connections For Differential Protection	38
Aim	38
Procedure A	38
Procedure B	39
Summary	39
Experiment 2 Internal Faults	42
Aim	42
Procedure A Phase to Phase (L-L) faults	42
Procedure B Phase to Earth (L-E) faults	43
Experiment 3 External Faults (through faults)	43
Aim	43
Procedure	43
Experiment 4 Differential Protection on Radial Circuits	46
Aim	46
Procedure	46
Experiment 5 Introduction to Switched Busbar Protection	49
Aim	49
Procedure	49
Experiment 6 Switched Busbar Zone Protection	52
Aim	52
Procedure A - One Zone	52
Procedure B - Two Zones	54
Procedure C - Overlapping Zones	56
Further Experiments	56